

6.40 For this problem we first need to convert engineering stresses and strains to true stresses and strains so that the constants K and n in Equation 6.19 may be determined. Since $\sigma_T = \sigma(1 + \epsilon)$ then,

$$\sigma_{T1} = (315 \text{ MPa})(1 + 0.105) = 348 \text{ MPa}$$

$$\sigma_{T2} = (340 \text{ MPa})(1 + 0.220) = 415 \text{ MPa}$$

Similarly for strains, since $\epsilon_T = \ln(1 + \epsilon)$ then

$$\epsilon_{T1} = \ln(1 + 0.105) = 0.09985$$

$$\epsilon_{T2} = \ln(1 + 0.220) = 0.19885$$

Taking logarithms of Equation 6.19, we get

$$\log \sigma_T = \log K + n \log \epsilon_T$$

which allows us to set up two simultaneous equations for the above pairs of true stresses and true strains, with K and n as unknowns. Thus

$$\log(348) = \log K + n \log(0.09985)$$

$$\log(415) = \log K + n \log(0.19885)$$

Solving for these two expressions yields $K = 628 \text{ MPa}$ and $n = 0.256$.

Now, converting $\epsilon = 0.28$ to true strain

$$\epsilon_T = \ln(1 + 0.28) = 0.247$$

The corresponding σ_T to give this value of ϵ_T (using Equation 6.19) is just

$$\sigma_T = K\epsilon_T^n = (628 \text{ MPa})(0.247)^{0.256} = 439 \text{ MPa}$$

Now converting this value of σ_T to an engineering stress using Equation 6.18a gives

$$\sigma = \frac{\sigma_T}{1 + \epsilon} = \frac{439 \text{ MPa}}{1 + 0.28} = 343 \text{ MPa}$$