

- (4) The alloy may continue to harden or overage at room temperature.