

4.31 (a) The interfacial defect that exists for this stacking sequence is a twin boundary, which occurs at the indicated position.



The stacking sequence on one side of this position is mirrored on the other side.

(b) The interfacial defect that exists within this FCC stacking sequence is a stacking fault, which occurs between the two lines.



Within this region, the stacking sequence is HCP.