

In summary, the procedure which can be used to produce the desired material would be as follows: cold work the as-received stock to 15.0 mm (0.591 in.), heat treat it to achieve complete recrystallization, and then cold work the material again to 12.7 mm (0.50 in.), which will give the desired tensile strength and ductility.